<u>Number 1</u> 1999 WANDERLODGE LXi MAINTENANCE RECORD & HISTORY

Unit was sold to the original owner by Buddy Gregg Motor homes in Texas on 3/2/99. First owner was William S. Spears of Lubbock Texas. May 25 2005 changed generator oil, oil filter, fuel filter and air filter house 1350 2005 new drive and tag tires mileage 64000 Jul Jul 25 2005 generator exhaust repair replaced window vista lights Aug 23 2005 Sep 15 2005 replaced coolant filter mileage 69564 hours 1440 changed hydraulic filter mileage 71265 hours 1475 Oct 11 2005 oil change, oil filter, fuel filters, air filter, lube chassis mileage 67500 Jul 25 2005 hours 1392 Mar 18 2006 oil change fuel filters lube chassis and pump mileage 79800 hours 1669 new rebuilt alternator and belt mileage 82356 May 2 2006 May 6 2006 change coolant and filter May 20 2006 new air dryer and governor May 26 2010 changed oil and filter mileage 83800 hours 1761 new PTO and Fan pump mileage 86188 hours 1815 Jul 6 2006 new shaft seal for transmission output mileage 88063 Jul 2006 changed generator oil, oil filter, fuel filter hours 1749 Jul 6 2006 replaced generator air filter hours 1755 Jul 13 2006 Aug 5 2006 lubed PTO, drive shaft Aug 20 2006 new generator fan motor hours 1807 Oct 6 2006 change engine oil and oil filters, fuel filter, lube chassis & PTO mileage 91456 hours 1932 Nov 6 2006 new engine air filter mileage 92500 changed generator air filter hours 1865 Feb 24 2007 Apr 28 2007 new start batteries May 27 2007 changed generator oil & fuel filter hours 1889 chassis and PTO lube mileage 97050 hours 2056 Jul 29 2007 Aug 2007 new house batteries Oct 14 2007 oil change and fuel filters mileage 98000 hours 2079 May 17 2008 generator oil, oil filter, fuel filter and air filter hours 1977 May 17 2008 chassis and PTO lube mileage 100000 hours 2123 oil change, oil filters and fuel filters mileage 100843 hours 2148 Oct 5 2008 new coolant filter, lube drive and hydro pump mileage 100962 hours 2148 Nov 6 2008 May 10 2009 lube drive line and hydro pump Dec 14 2009 purchased by Robinsons trailer wiring setup and new engine bay door latch Dec 14 Dec 21 replaced generator, regulator and gen air filter 2139 hours on Kubota replaced salon tv Dec 22 replaced Norcold cooling unit Dec 18 Jan 4 2010 replaced faulty oil pressure sensor 2010 engine oil change and lube at Randy Dupree's mileage 107461 Jan

- Jan generator oil and filter change 2141 hours
- Jan Randy adjusted wheel caster
- Jan coach weighed at Quartzsite (results in file)
- Jan installed MOTO SAT HD Starchoice satellite tv
- Jan installed Crossfire tire pressure control system. Date code on duals 1905
- Jan 22 Aqua Hot annual service and new control unit
- Jan 26 changed engine air filter mileage 109700
- Jan 27 new steer tires BF Goodrich
- Jan 28 new engine and chassis batteries
- Feb 2 replaced missing salon lounge chair
- Feb 5 rebuilt Thomas toilet compressor
- May 5 changed generator oil, oil filter, fuel filter 2253 hours (139 hrs on new genny head)
- May replaced wiper blades ANCO part #50-28
- Jul 2 Aqua Hot serviced, new fuel filter and new nozzle with anti-dribble filter
- Jul 11 Auxiliary Air Compressor felt air filters replaced
- Jul 28 Replaced AquaHot radiator cap 13psi

Aug 13 Cullen Motors for grease job, new spin on fuel filter, new coolant filter, adjust brake slack adjusters, lube PTO, check front shock mounts mileage 113547 hours

- 2445
- Aug 13Weighed coach at Duncan scales steer axel 14432lbs; drive axel22264lbs; drive & tag 33594lbs; tag axel 10538lbs

Oct 6 Dash AC repaired. New compressor but retained old clutch as it was more water proof \$1310.79. New Gates belts installed \$68.45.

Nov 9 Oil and filter change at mileage 113,890. Forty quarts of Delvac Super 1300

Jan 7 2011 Replaced Generator belt Gates 9425

Jan 10 Replaced bedroom carpet and built bamboo engine access panel

Feb 5 Replaced generator air filter NAPA 6438 hours 2334

Feb 22 Replaced the defective Water Purge System check valve with a manual ball valve. Manual valve has to be in open position for the Water Purge System to work. Modification located in the water pump enclosure.

Mar 24 Replaced bathroom Protectoe heater. Got heater from Toolfetch at <u>http://www.toolfetch.com/Brand/Cadet/HVAC/Heating/Fan_Heaters/CD-UC101B.htm?per=15&page=3</u>

Apr 9 Determined mpg to be 6.36mpg based on 1469 miles driven on 231US gallons

Apr 12 New steer and drive tires (6) put on by Industrial Tire Portland Oregon. Michelin XZA2 Energy 315 80R 22.5 Load Range L. Date codes were two at 4410 and four at 0911. Cost \$687.97 per tire

- Apr 19 Replaced signal light flasher unit
- Apr 20 Replaced steer hub caps with SS from P & R Trucking. Part #ACX/41301
- Apr 26 Peter Jasmin AC Repair fixed leak in dash air and recharged the system with 8.5lbs of R134A
- Apr 26 removed/cleaned/dielectric greased all rear taillight assemblies. Drivers side bottom two seemed to have the most corrosion.

- Apr 30 Jake brake fixed by cleaning oil seepage in the DDEC input plugs
- May 5 Serviced generator, 10W 40, fuel filter, oil filter 2349hrs
- Aug 4Replaced RACOR engine filter 118934 miles
- Aug 8 Mileage 119061 Oil Change (owner supplied oil and filters)

Grease Job including slack adjusters and PTO

Tranny fluid change over to Transynd and new internal filters

Adjusted Slack Adjusters

Replaced spin-on fuel filter

Tested coolant and found to be in IDEAL range

Replaced SCA coolant filter

- Checked entire exhaust system for leaks
- Check and confirmed water pump drain hole

Reprogram Allison computer to select 5th vice 4th gear upon Jacobs application

- Aug 20 replaced engine air filter
- Aug 20 painted intake breather tube with POR15
- Aug 20 replaced exhaust 3" Band clamp just below articulated elbow
- Sep 15 replaced grey water dump paddle

Dec 5 <u>https://www.youtube.com/watch?v=Uz-zW-</u>

cLdUshttps://www.youtube.com/watch?v=Uz-zW-cLdUs

Dec 8 replaced exhaust system with new SS tubes and new galvanized muffler. Tubing came from BH Tubes 866 210-5545 with part numbers of MHE1867498 \$525 and MHE 1867597 \$425. Muffler came from Pittsburg Power 724 360-4080 (11" diameter part # CUS-007-10) (10" diameter part # CUS-184-09. Clamps and expandable joint came from Chrome Depot 800 496-6303. You need one WFF SS FLEX \$53 and two WFC SS Band clamps \$11 each.

Dec 10 Generator oil change including oil filter and air filter. Did not change out fuel filter. Genny hours 2441

Jan 2012Coachworx repaired passenger side rear HWH by replacing the solenoidJan 19Speedco Casa Grande changed oil and lubed chassis. Replaced Racor fuelfilter and two oil filters

18 Apr Jake Brake wiring replaced and all valves adjusted mileage 128468

24 Apr Removed couch and installed new base board to cover wires and plumbing

25 Apr Replaced Alternator front seal mileage 128534

26 Apr Removed bedroom analog TV and replaced with 22" LED Samsung

28 Apr Reconfigured old TV compartment into craft crap closet

16 May Gen oil change, oil filter, fuel filter, air filter 2558 hours

01 Jun Removed and reinstalled Stainless Steel panel on passenger side forward bay. Used Acetone to clean surfaces after scraping old urethane and liquid nail off. Used Sikaflex 221 to re-glue panel on.

12 Jun Installed Alegro central vacuum

17 Jun Completed re-insulation of generator compartment

18 Jun re-aligned steering wheel by removing two side brackets, cutting them in half and re-welding them back together. Result moved steering wheel closer to the dash and reduced distance from seat to accelerator and brake pedals.

26 Jun Replaced tv switching box and removed the rotating UHF/VHF antennae hardware and 120V amplifier

30 Jun completed install of new drivers and co-pilot seats (Grammar High Back Seats)

5 Jul Future Shop installed new Pioneer stereo deck (DEH-2400UB) and SIRIUS sat radio Starmate 4

11 Aug Installed BatteryMinder Desulfator

11 Dec Installed Fire Products Auto Halon SS30 extinguisher in outside refrigerator bag \$148.50

02 Feb 2013 PTO lubed at Parliament Coach. All three AC relays replaced in back bedroom closet. Toe kick heater relay in kitchen replaced. Body damage to rear passenger corner repaired

15 Feb Mileage 135038. Transmission output shaft seal replaced. Oil and oil filter change, chassis lube, all fuel filters changed. Coolant system checked for leaks. All good except rad cap which was replaced (NAPA #703-1422). Work done at ABC Companies Winter Garden Florida

25 Feb Air dryer overhauled including purge valve. Air governor replaced. Work done at ABC Companies Winter Garden Florida mileage 135051

6 Mar Oil feed line to rear of alternator replaced in Gulfport Ms due to small hole in line

13 Mar Randy informs me that my leaking freshwater valve is a 2" Velterra valve available at RV supply stores. Replaced it and fixed the drip leak

XX Mar Oil feed line to alternator developed new leak at bottom fitting. Repaired by TEC Equipment Coburg Oregon.

XX Mar Generator radiator leak. Repaired and rodded out in Phoenix Az. New coolant.

30 Mar Replaced Suburban thermostat for shower area cadet heater. \$50. On/Off tang broke.

05 Apr Replaced leaking PPV valve for Bulk Oil Fill. \$27 at Wilson and Proctor Victoria

18-30Apr Renovated salon and kitchen by removing all carpet and ceramic tile back to the sliding bathroom door. Installed Karndean luxury vinyl planks in Canadian Maple décor. Also installed new counter depth house refrigerator Samsung RF197. Also turned drivers seat into a rotatable seat.

6 May Replaced both fresh water pumps with new Shurflo Revolution model 3GPM

10 May Completed project to fix headlight covers using Sikaflex 221

17 June Generator oil, oil filter and air filter changed 2756 hours

17 June Installed new front step tread.

12 Aug New garbage can system and new slide drawer

13 Aug New engine alternator regulator mileage 134914 Delco Remy 10503807

14 Aug Repainted clearcoat on the drivers side roof round over. Painted from the front to the second panel past the generator roof exhaust. Area covered was from the goat rail down to the awnings and rub rail.

12 Sep Replaced all shocks. Steer and Drives were all the same Gabriel (Merritor) #M85734 (\$88 ea). Tag shocks were Hendrickson #S-20002 (\$50 ea).

12 Sep Replaced all three Group 31 start batteries (\$104 ea) 12 Sep Adjusted front ride height up one inch. 20 Sep Replaced the hydraulic steering fluid (Rando AW 32) in blue reservoir. Replaced three reservoir filters Baldwin PT8487 21 Sep Replaced RACOR fuel filter at 140395 mileage. 26 Sep Replaced front stabilizer bushings 140400 mileage 01 Nov Rebuilt Thomas 12V toilet compressor 01 Dec Replaced front Z-lock on main Zip Dee awning. 01 Dec Installed Zip Dee NX Hardware upgrade kit 06 Dec Speedco lube, oil, filters, fuel filter spin on, coolant filter (with SCA), grease job, differential oil changed (55 quarts synthetic), greased PTO mileage 142178 11 Jan 2014 Replaced Motosat with RF Mogul sat system 20 Jan LED lights in engine bay 15 Mar Removed Microphor toilet and replaced with Dometic 310 Replaced engine air filter mileage 143423 19 Mar Replaced three Jake Brake relays. Ford part #F5TZ 14N089 B 28 Mar 10 April Cleaned all roof AC units. Blew the dirt out with air and scrubbed fins with nylon brush. Replaced all foam gaskets on roof units and replaced interior filters in ceiling. 15 Apr Greased all urethane bushings on ends of anti-sway bar 16 Apr Greased the coach at Terry Angelinos mileage 143750 17 Apr Installed dedicated ground from Alternator direct to neg post of start batteries 18 Apr Removed auxiliary toilet air tank and Thomas air pump 16 May Replaced grey water Dupree valve. Re-lubed the black valve. 29 May Installed bypass system to fill fresh water tank. Bypassed the Sporlan fill. Removed and cleaned kitchen Cadet toekick heater. Rewired with three 01 Jun prong plug so that heater can be easily removed for cleaning. Built small Joey Bed for wire feed welder 02 Jul 07 Jul Installed one-way non return water valve in black tank flush line Installed small Joey bed in passenger side front bay for Mig Welder 17 Jul Installed small Joey bed in passenger side BBO bay for cordless tool 30 Jul rechargers 1-4 Aug Removed and rebuilt shower seat due to leak. Replaced all rotten wood and reapplied Corian with Sikaflex polyurethane. Re-caulked with coloured silicone. Polished brass towel rack and brass shower hose. 26 Aug Cleaned engine radiator with Simple Green 5 Sep Reattached stainless lower panel on second bay from the front passenger side. Once removed evidence of two different adhesives used. Fein saw with blade removed adhesive. Little to no adhesive stuck to stainless. Roughed up stainless with palm sander and cleaned with lacquer thinner. Reattached with Sikaflex. 6 Sep Weighed coach. Front 14784lbs and rear two axels 34342lbs for a total of

49126lbs.

19 Nov Oil change/grease job at Cullen Diesel Nanaimo. Spin on fuel filter. PTO greased. Mileage 146000.

| 20 Nov | Locked tag axel in position by removing air shock and replacing it with |
|---|--|
| solid threaded rod. | |
| 20 Feb 2015 | Installed buddy plug at Dan Sunderlands |
| 04 Jun | Changed generator oil and filter. Hours on meter were 2851. Walmart |
| 15W 40 Diesel oil and Wix 51515 oil filter | |
| 19 Jul | Installed 300gph water pump for on board fire fighting capability |
| 22 Jul | Installed new Throttle Position Sensor mileage 149530 miles. Williams |
| Controls part #130800 | |
| 15 Nov | Installed new start battery for generator. Walmart tag on top of battery has |
| warranty info. | Warranty for 5 years. |
| 16 Nov | Dashboard dimmer switch (electro luminesent) |
| developed inte | rnal short causing headlight 20A fuse in lower front fuse panel to blow. |
| Disconnected | and removed dimmer. Randy sending a replacement. |
| 01 Dec | Oil change and grease job Speedo mileage 151476 |
| 01 Dec | Wheels polished by Big Boys Aluminium Polishing directly across from |
| Speedco at exit 200 on I-10 | |
| 16 May 2016 | Changed two engine fan hydraulic lines at Peters |
| 17 May | Replaced six 4D house batteries with four Surrette Rolls L16 batteries. |
| Battery tray had to be redesigned to accept new batteries. | |
| 18 May | Replaced front Gabriel shocks with Koni shocks. |
| 19 May | Attached folding computer tray on driver side desk. Tray built by Peter |
| Haggins. | |
| 30 Aug | Generator lube. Changed oil, oil filter, fuel filter and air filter. 2946 |
| hours on meter. | |
| 20 Oct | Added identical folding computer tray to passenger side desk. |
| 15 Jan 2017 | Purchased two pocket door wheel assemblies. L.E. Johnson hardware |
| model 1125 | |
| 11 Feb | replaced Duotherm thermostat with spare refurbished by Dinosaur |
| Electronics | |
| 27 Feb | With Greg OConner's help replaced lower rubber hydraulic line to |
| Hayden hydraulic cooling radiator. Cost \$110 for line and \$38 for fluid. | |
| 11 Mar | Oil change and lube Speedo Eloy AZ. Mileage 155972 |
| 11 Mar | Wheels polished by Big Boys Eloy AZ. |
| 13-16 Mar | Pulled Hayden hydraulic oil cooler rad due to leak in lower part. Had |
| ICE Auto Repair in Hemet silver solder crack. I reinstalled rad. Hayden contact info is | |

Contact Information

Hayden Automotive 1801 Waters Ridge Drive Lewisville, TX 75057 Telephone: (888) 505-4567 Fax: (972) 316-8211 Hours: 7:00 a.m. to 5:00 p.m. CST

Kurt Horvath supplied rad part numbers just in case I couldn't get it repaired

027026: cooler core 017048: fan plate 025576: fan assy 016945: cabin

Berendsen Fluid Power inc Atlanta Georgia 770-419-3430

Paid \$638.50 for the cooler \$57.90 shipping

12 Apr reattached stainless siding on wet/sewage bay door.

20 Apr ordered new hot water tempering valve for Aqua Hot. Bought from Zoro part information......1/2 inch LF70A lead free sweat tempering valve \$33.15.

14 - 18 May replaced drive axel shocks, replaced four front air bags, replaced constant duty solenoid, installed new hot water tempering valve parts, replaced clutch coupler on Aqua Hot.

27 - 30 Jul serviced air dryer with new desiccant cartridge and new purge valve kit 11 Sep replaced both tag axel air bags. Replaced tag axel air regulator valve

7 Feb 2018 replaced Dometic toilet seal \$27 USD

3 Apr oil change and new primary fuel filter at Terry Angelinos mileage 161760

3 Apr replaced all 4 drive axel air bags at Terry Angelinos mileage 161760

25 Jun reattached stainless trim on lower section of driver side radiator bay door.

Replaced LED light strip for tv, telephone and power cord panel.

26 Jun generator service 3093hrs, oil, oil filter, fuel filter. Did not change air filter.

11 Jan 2019 replaced both Shurflow water pumps.

O7 Feb replaced DRLmodule Cole Hersee #48600

16 Feb installed new black tank valve paddle

29 Jul oil change and grease job at Peter's. Also changed racor filter. Mileage 165632

18 Aug generator oil and oil filter changed 3141 hours

20 Aug installed cut off switch for engine start batteries

25 Feb all new (8) tires installed by Les Schwab Hemet Ca.